



INSTRUCTION SHEET

CSS - Cable Suspension System



Mounting

1. Install a wet location surface mount junction box in desired location.
2. Install 1/4-20 studs (by others) suitable for intended surface as shown.
3. Attach side exit grippers (A) to 1/4-20 studs (by others).
4. Install studs (B) into fixture endcaps.
5. Insert cables (D) into cable couplers (C) and attach to studs (B).
6. Insert cables (D) into side exit grippers (A) and adjust to desired height.
7. Connect SO cord (E) to junction box. **Note:** Pipe thread sealant or teflon tape must be used on threads.
8. Make wire connections inside junction box and install cover. Tie wrap SO cord (E) to cable (D).

\*To service driver/ballast compartment or to install lamps, continue to step 10

10. Loosen captive screws (F) and remove endplates (G) from both ends.
11. Remove lens by lifting from end. Use a flat blade screw driver (H) to pry loose. **Note:** take care not to damage lens or gasket.
12. Remove reflector/liner.
13. Service as required.
14. Reinstall reflector/liner.
15. Reinstall lens. **Note:** firmly press along entire length of lens to ensure a good seal.
16. Reinstall both endplates (G).

**Note:** To be installed by a qualified electrician per N.E.C. and all local codes.

820-00035  
V-0615