





Thank you for purchasing our lighting fixture.

Please clean with a soft, dry cloth ONLY! Do not use cleansers.

www.hudsonvalleylighting.com

INSTALLATION INSTRUCTIONS

5009, 5012, 5015

GENERAL

- 1. To ensure successful installation, the following instructions and diagram(s) should be read and understood.
- 2. All electrical connections must be made in accordance with the National Electric code and local codes and ordinances. If you are uncertainnow to install electrical wiring and lighting fixturessecure the services of a qualified licensed electrician.

TOOLS NEEDED

Blade screwdriver, phillips screwdriver, slip joint pliers or small adjustable wrench, wire cutter/stripper, electrical current tester, stepladder and electrical tape.

INSTALLATION PRE PARATION

- 1. TURN OFF THE ENTIRE ELECTRICAL CIRCUIT TO WHICH THE LIGHTING FIXTURE IS TO BE ATTACHED. Turn circuit breaker to the off position or completely remove the fuse controlling the circuit.
- 2. If an existing fixture is being replaced, remove it andnote to which of the wires in the outlet box the fixture was attached. DO NOT SEPARATE MULTIPLE TWISTED WIRES THAT MAY BE IN THE BOX. DO NOT DAMAGE THE INSULATION OF OLDER WIRING. In regular circumstances the BLACK wire will be the "Hot" lead and the WHITE wire will be the "Neutral" or "Common" lead. A GREEN or BARE COPPER wire is the "Ground". In older buildings it is always good practice to reconfirm the polarity
- 3. This fixture is designed to be mounted on an octagon box. The box must be securely mounted to the structure of the building.

FIXTURE INSTALLATION

- 1. Remove the fixture and parts bag(s) from the carton. Before discarding the carton, double checkto make certain that all parts are found.
- 2. Attach the mountingbar to the outlet box. (The green screw should face out). Pull wires out of box. T hread the nippleonto the mountingbar.
- 3. Attach the shade ring to the fixture, secure it by the adjustable nut.
- 4. Measure 6" of lead wire beyond the end of the chain. Cut off excess wire. Strip the insulation off the ends of the leads exposing approx. 1/2 " of wire. Twist the strands of wire together. Push the leads and ground wire upthrough the screwcollar loop and nipple and into the outlet box.
- 5. Fasten the bare ground wire to the green or bare copper wire in the outlet box or the green screw on the crossbar.

NEVER FASTEN THE GROUND WIRE TO THE BLACK OR "HOT" WIRE! FAILURE TO FOLLOW THIS INSTRUCTION COULD RESU SERIOUS INJURY OR DEATH!

LTI N

- 6. Fasten the fixture lead with the ridge(s) to the white wire in the outlet box. Fasten the wires together with an approved fastener (wire nut)Starting about 1" below the fastener, tightly wrap the connetion withelectrical tape so that the tape seals the end of the fastener. Make sure that t here is no exposed wire or strands that could cause a dangerous short circuit!
- 7. Connect the smooth fixture lead to the black wire in the outlet box. Fasten the joined wires as in step 5.
- 8. Slide the canopy &screwcollar ring up the chan & secure canopy to the ceiling.
- 9. Thread the fixture loop onto the fixture, twist the center column onto the nipple on the wire box
- 10. Open end links of chain and attach the chain to the loopClose the top link of chain. Hang the fixture on the chain at the desiredheight. Remove excess chain. Close the bottom link of chain.
- 11. Install the lamps (light bulb). NOTE: 5009 is rated for 75 watt type A. 5012 is rated for 100 watt type A. 5015 is rated for 75 watt type A.
- 12. Attached the glass to the fixture and secure it by the glass screws.
- 13. Restore power to circuit at breaker or fuse box.

DO NOT EXCEED RECOMMENDED WATTAGE!

NOTE: The important safeguard and instructions outlined on his sheet are not meant to cover all possible conditions and situations that may occur. It must be understood that common sense, cation and care are factors that cannot be built into any product. Caution and care must be supplied by the person(s) installing, operating and maintaining this lighting fixture.